DMS 1819 B¹2, B¹2K, B2, B2K, B2PF,

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1 87

B2PF

MATERIAL SAFETY DATA SHEET

MAY 26 1982

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917) DNG 1819 B/2K

<u> </u>				- 2/N) 10		7-7
		SECT	ION I			
MANUFACTURER'S NAME Essex Chemical Corp.				EMERGENCY TELEPHONE (213) 537-76	NE NO. 5 0 0	
ADDRESS (Number, Street, City, State, and ZIP C 19451 Susana Rd., Compto	ode)	CA 902	21	<u> </u>		
CHEMICAL NAME AND SYNONYMS N/A	,			AME AND SYNONYMS Seal 735 Accele	erato	or/
CHEMICAL FAMILY N/A			FORMULA N/A	and the process of the state of	Felderbelt er sterke versyen er seine	The same of the sa
SECTION	V 11 -	HAZAR	DOUS INGREDI	ENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND	METALLIC COATINGS	%	TLV (Units)

<u> </u>	•	<u> </u>	(Units)			(Units)
PIGMENTS				BASE METAL		
CATALYST	Lead peroxide 55-6	0%		ALLOYS		
VEHICLE				METALLIC COATINGS		
SOLVENTS				FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES	****		-	OTHERS		
OTHERS						
	HAZARDOUS MIXTURES	OF (OTHER LIC	DUIDS, SOLIDS, OR GASES	%	TLV (Units)
			:			
			:		1	

SECTION III - PHYSICAL DATA					
BOILING POINT (°F.)	N/A	SPECIFIC GRAVITY (H2O=1)	2.2		
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT, VOLATILE BY VOLUME (%)	0		
VAPOR DENSITY (AIR=1)	N/A	EVAPORATION RATE (=1)	N/A		
SOLUBILITY IN WATER	Ni1				
APPEARANCE AND ODOR Brown	aste, slight	odor			

XPLOSION HAZARD DAT	Ά	
FLAMMABLE LIMITS N/A	Lel	Uel
O . water		
4		
N-		
3		
		N/A O ₂ , water

	5.	SI	ECTION	I V	- HEA	LTH HAZARD	DATA
THRESHOLD LIMI		known					
EFFECTS OF OVE	REXPOSURE						and headache.
		TIIB	esteu	-112	usea	vomiting	and neadache.
EMERGENCY AND	FIRST AID	PROCEDU	IRES ,			3	
						consult	physician
							
	*		SECTIO	אכ	/I - R	EACTIVITY DA	TA
STABILITY	UNSTAB	UNSTABLE		CONDITIONS TO AVOID			
	STABLE		X	T			
INCOMPATABILIT	Y (Materials	to avoid)	Stro	no	redu	cing agents	
HAZARDOUS DEC	OMPOSITIO	N PRODUC					-
	T	T				CONDITIONS TO	AVOID
HAZARDOUS POLYMERIZATION	v —	AY OCCUP			37		
	WI	LL NOT C	CCUR		X		
	······································						
STEPS TO BE TAK		MATERI				OR LEAK PROC	spillage with rags or
		<u> </u>					
WĄSTE DISPOSAL	метнор	3 1 1.			· !		state and local
<u>waste disp</u> regulation:		uld be	in acc	conc	ance	with Tederal,	state and local
	T	···					
	SE	CTION	VIII - S	SPE	CIALI	PROTECTION IN	IFORMATION
RESPIRATORY PR							
		XHAUST	• /				SPECIAL
VENTILATION		IICAL (Gei	norall			;	OTHER
						1 5 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	
	Neoprer					EYE PROTECTION	afety goggles.
OTHER PROTECTI	VE EQUIPM	Co	veral	1s,	apr		
		SI	ECTION	J IX	- SPE	CIAL PRECAUT	TIONS
PRECAUTIONS TO	BE TAKEN	IN HAND	LING AN	D ST	ORING	Avoid conta	ct and ingestion.
, , , , , , , , , , , , , , , , , , ,							
Store in	closed	l_cont	ainer	be	low	80°F.	
	Υe	ellow	label	. ma	ateri	Lal.	

PAGE (2)

Form OSHA-20 Rev. May 72